







2000 Falcon 2000 | N26PA*

Serial Number 117

Airframe Total Time (as of 11/27/17) 9,055.3 Hours 6,122 Landings

Engine Total Time (as of 11/27/17)

#1 8,853.8 Hours 6,003 Cycles Engines Honeywell CFE738-1-1B Engines on CSP Gold

#2 8,816.2 Hours 5,966 Cycles 47.2 Hours since MPI/CZI

APU Total Time (as of 11/27/17) 4,225 Hours APU Honeywell GTCP36-150(F2M)

Contact Brad Stancil +1 (317) 815-9403 Info@HolsteinAviation.com

*Owner to retain registration number

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Aircraft Highlights

- U.S. Fortune 50 Pedigree
- Engines on CSP Gold \$504.72 / Hour per Engine
- TCAS II with Change 7.1
- Airshow 4000 / Wi-Fi
- Dry Bay Mod
- Excellent Paint & Interior
- CAMP Maintenance Tracking
- No Known Damage History

Inspection & Maintenance History

- 1B Inspection next due @ 9600 hours
- 2B Inspection next due @ 9600 hours
- 3B Inspection next due @ 9600 hours
- 1C Inspection complied with @ 4331 cycles/May 2012; next due @ 8081 cycles/May 2018
- 2C Inspection complied with @ 4331 cycles/May 2012; next due @ 11831 cycles/May 2024
- 3C Inspection due @ 8081 cycles/May 2018
- Landing Gear Overhaul complied with @ 4331 landings/June 2012; next due @ 10331 landings/June 2024
- LH Engine HSI complied with @ 6354.9 engine hours/April 2012; next due @ 8854.9 engine hours
- LH Engine OVH complied with @ 4087.8 engine hours/Sept 2007; next due @ 9087.8 engine hours
- RH Engine HSI complied with @ 8769.0 engine hours/October 2017; next due @ 11269.0 engine hours

RH Engine OVH complied with @ 8769.0 engine hours/October 2017; next due @ 13769.0 engine hours *Note: Aircraft is on a "Block Inspection" thru Falcon.



Avionics

Collins Pro Line IV Avionics Dual Collins ADC-850C Air Data Computer **Dual ADF-462 Modules** Collins APS-4000 Autopilot Honeywell Solid State Cockpit Voice Recorder **Dual Collins VHF-422C Transceivers** Honeywell AFIS Honeywell Mark V GPWS with Windshear Detection **Dual DME-442 DME Modules ELT-97** Honeywell Solid State Flight Data Recorder **Dual Collins FMC FMS-6100 Dual Collins GPS-4000** Dual Collins HF-9000 Transceivers Dual Honeywell Laseref IV **Dual Collins VIR-432 Navigation Modules** Dual Collins ALT-55B Radio Altimeter Honeywell TTR-920 TCAS II w/Change 7.1 Dual Collins TDR-94D Mode S Transponders Collins TWR-850 Weather Radar

Features and Options

Airshow 4000 Cabin Video System Forward 17.5" Bulkhead Monitor Aft 15" Bulkhead Monitor CD/DVD Entertainment System Aircell High Speed Internet (WLAN) Aircell Axxess II Two Channel PBX Iridium Satellite Wi-Fi Dry Bay Mod CAMP Maintenance Tracking Program



Exterior – New Paint – May 2012 by Duncan Aviation, Battle Creek

Overall Matterhorn White with Black, Gamma Gray and Flight Red stripes



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Interior – Refurbished May 2012 by Duncan Aviation, Battle Creek

Ten passenger executive interior features a forward 4-place club with folding tables and an aft 4-place conference table facing a 2-place club seating area. The aircraft is also equipped with a forward galley, aft lavatory and 3rd crew seat in the cockpit. The forward galley is equipped with a hi-temp oven, microwave oven and coffee maker.



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.















Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.





Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Cockpit



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

- END-