



1985 Falcon 20-F5 | N404HR

Serial Number 455



Airframe Total Time (as of 3/19/18)

12,742.4 Hours

10,260 Landings

Engine Total Time (as of 3/19/18)

#1 10,657.8 Hours

8,635 Cycles

#2 10,502.9 Hours

8,373 Cycles

APU Total Time (as of 11/3/17)

5,242 Hours

Engines

Honeywell TFE731-5BR

Engines on MSP

APU

Garrett GTCP 36-150



Contact Michael Gauvreau

+1 (317) 815-9403

Info@HolsteinAviation.com

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Aircraft Highlights

- Engines on MSP
- Gear Overhaul - July 2016
- C Check - October 2014
- Thrust Reversers
- Honeywell Mark VII EGPWS with Windshear
- Dual Aircell ST-3100 SATCOMs
- CAMP Maintenance Tracking
- No Known Damage History

Inspection & Maintenance History

A Inspection complied with Nov 2017 @ 12732.8 hours; next due @ 13032.8 hours / April 2018

2A Inspection complied with Nov 2017 @ 12732.8 hours; next due @ 13332.8 hours / Oct 2018

2A+ Inspection complied with November 2017; next due October 2018

Z Inspection complied with @ 12722.7 hours; next due @ 15122.7 hours

B Inspection complied with @ 12635.1 hours; next due @ 13835.1 hours

2B Inspection complied with @ 11351.8 hours; next due @ 13751.8 hours

3B Inspection complied with @ 9917.5 hours; next due @ 13517.5 hours

4B Inspection complied with @ 8901.2 hours; next due @ 13701.2 hours

C Inspection complied with October 2014; next due October 2020

2C Inspection complied with September 2008; next due December 2020

MLG Detailed Inspection complied with July 2016 @ 10234 landings; next due @ 20234 landings / Nov 2030

LH Engine MPI/HOT complied with @ 9360.1 engine hours; next due @ 11860.1 engine hours

LH Engine CZI/OVH complied with @ 7570.3 engine hours; next due @ 12570.3 engine hours

RH Engine MPI/HOT complied with @ 10395.6 engine hours; next due @ 12895.6 engine hours

RH Engine CZI/OVH complied with @ 10395.6 engine hours; next due @ 15395.6 engine hours

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Avionics

Dual Collins FD-109 IFCS / Pro Line II
Dual Collins ADF-60
Collins AP-105 IFCS Autopilot
Dual Collins VHF-22 w/8.33 MHz spacing
Fairchild GA100 Cockpit Voice Recorder
Dual Collins DME-40 DMEs
Dual Collins FD-109 IFCS Flight Director
Dual Honeywell GNS-XLS w/GPS & P-RNAV capability
Dual Collins VIR-32 w/FM Immunity
Collins ALT-55 Radar Altimeter
Dual Aircell ST-3100 SATCOMs
Honeywell Mark VII EGPWS w/windshear
Collins TCAS-II w/Change 7
Dual Collins TDR-94D Transponders
Honeywell Primus 400 Weather Radar

Features and Options

Kollsman Digital Pressurization Controller
Artex 406 ELT
IS&S Air Data & Altimeters
BF Goodrich GH-3000 Standby Instruments (coupled to FMS & VOR/ILS)
Thrust Reversers
Windshield Embellisher Mod
Heavy Landing Gear
SAFT Batteries
Large Aft Baggage w/PATS APU Installation
Tel-Tail Lights
CAMP Maintenance Tracking
RVSM
RNP-10

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Exterior – New Paint in 2008 at West Star Aviation, East Alton, Illinois



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Interior – Interior refurbished in 2008 at West Star Aviation, East Alton, Illinois

Fireblocked tan leather executive ergonomic articulating seats. Matching carpeting. Figured high-gloss veneer cabinetry. Entertainment system with Airshow 400, DVD player with dual screens and 6-disc CD player. 110 outlets in the cabin. Externally-serviceable lavatory.



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Interior – continued



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Interior – continued



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Interior – continued



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com

Cockpit



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

- END -

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • www.holsteinaviation.com