







2005 Beechcraft Premier I | N84VA

S/N RB-134

Airframe Total Time (as of 3/5/20)

4,607.7 Hours 4,018 Landings

Engine Total Time (as of 3/5/20)

#1 4,428.4 Hours 3,915 Cycles 20.3 TSO

#2 4,520.0 Hours 3,980 Cycles

20.3 TSO

Engines

Williams FJ44-2A Engines on TAP Advantage Blue

5000 Hour TBO

Contact Jim Holstein +1 (317) 815-9403 Info@HolsteinAviation.com

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Aircraft Highlights

- One Owner Since New
- Engines on TAP Advantage Blue \$164.51 per Hour per Engine
- Avionics on CASP \$80.94 per Hour
- Collins TCAS 4000 / TCAS II
- ADS-B In & Out Compliant
- TDR-94D Transponders with Elementary Surveillance (Flight ID)
- Mark V EGPWS
- Maps, Charts, Weather & Traffic on iPad
- Cockpit Sliding Door
- Fresh Engine Overhauls October 2019
- Recent 600/1200 Hour A & B Inspections December 2019
- CAMP Maintenance Tracking
- No Known Damage History

Inspection & Maintenance History

A 600 Hour Inspection complied with @ 4585.1 hours; next due @ 5185.1 hours B 1200 Hour Inspection complied with @ 4585.1 hours; next due @ 5785.1 hours MLG Gear/Structure Inspection due @ 5000 cycles LH Engine OVH complied with @ 4,405.8 engine hours; next due @ 9,405.8 engine hours RH Engine OVH complied with @ 4,497.4 engine hours; next due @ 9,497.4 engine hours A/C 205.06 hours as of 3/5/20

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Avionics

Collins Pro Line 21 Avionics w/3 Tube 10x8 Inch EFIS Displays

Dual Collins AHC-3000 AHRS

Single Collins FMS-3000 Flight Management System with Database

Dual Collins ADC-3000 Air Data Computers

Dual Collins VIR-432 Nav Receivers

Single Collins ALT-4000 Radio Altimeter

Single Collins DME-442

Single Collins ADF-462

MDC-3000 Maintenance Diagnostic Computer

Collins WXR-800 Weather Radar

Dual Collins dB System Model 438 Audio Systems

Dual Collins 4000S GPS

Features and Options

ADS-B Out

Honeywell Mark V EGPWS

Artex C406-2 ELT

Three Tube EFIS Display Format

Collins TCAS 4000/TCAS II with Dual Collins Mode S TDR-94D Diversity Transponders with

Elementary Surveillance (Flight ID)

Dual Collins VHF-422C Comm System

Two Personal Computer Power Outlets (110 VAC)

Aft Baggage Heat

Leather Table Work Surface

Enclosed Window Shades

Remote Low Engine Oil Sensor System

Right Side Ice Light

77 Cu. Ft. Oxygen System

Remote Control Entry Lighting

Aft Maintenance Bay Lighting

Refreshment/Hang up Baggage Cabinet

Cockpit Sliding Door

Smoked Nickel Plating

Relief Tube in Cockpit & Lavatory

BOW 8,497 lbs.

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Exterior - Overall Matterhorn White with Black Metallic and Red Accent Stripes





Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Interior -

Headliner: Light Oyster stretch

Console cap: Birch leather

Upper console: River Sand Marshall fabric

Lower console:

Upper partition mirror:

Floor covering:

Birch leather

Bronze Jet Mirror

Latte Frieze carpet

Table work surface: Birch leather Cabin / cockpit chairs: Birch leather

Chairs – belt/harness: Fawn

Metal plating: Smoked Nickel

Laminate: Showcase Mahogany



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Interior - continued





Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Interior - continued





Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Cockpit



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.