# 2002 Beechjet 400A, S/N RK-339





Casey Blake +1 (317) 815-9403 Info@HolsteinAviation.com



S/N RK-339 N404LR

#### **AIRCRAFT LISTING DETAILS:**

Total Hours: 2,975.3

Total Landings: 2,302

Engines: Pratt & Whitney JT15D-5

#1

#2

Total Hours: 2,975.3

2,975.3

**Engine Cycles:** 

2,302

2,302

JA0455

Serial Numbers:

JA0459

#### **AIRCRAFT HIGHLIGHTS:**

- Four U.S. Owners Since New
- Low Total Time
- Pro Line 21 Nextant XTi Upgrade (\$475K Value)
- ADS-B / Integrated Charts / Synthetic Vision / XM Weather
- New Paint & Interior 2010 by Elliott Aviation
- TRAXXALL Maintenance Tracking Program
- No Known Damage History

#### **AVIONICS:**

- Collins Pro Line 21 Avionics Suite
- Collins FCS-4000 Autopilot
- Dual Collins AMS-5000 w/GPS 4000A Sensor FMS
- Dual Collins VHF-422C w/8.33 Spacing VHF Communication
- Dual Collins VIR-432 VHF Navigation
- Collins ADF-462 ADF
- Dual Collins DME-442 DME
- Dual Collins SDU-640B RMI
- Dual Collins TDR-94D Transponders
- Collins TWR-850 Doppler Turbulence Avoidance Radar
- Dual DB System Model 438 Audio Systems
- Collins ALT-55B Radio Altimeter
- L3 FA-2100 Cockpit Voice Recorder
- Artex 406-1 ELT
- Collins TCAS-II TTR-920 w/Change 7
- Honeywell MK-V Terrain Avoidance
- Garmin 696 GPS
- Garmin 696 XM Weather
- Garmin 696 Charts
- Synthetic Vision

S/N RK-339 N404LR

#### **FEATURES/OPTIONS:**

- Thrust Reversers
- Tail Logo Light
- Freon Air Conditioning
- Penny & Giles Cabin Display
- Cabin A/C Outlets
- ADS-B Out (integrated with Pro Line 21)

#### **INSPECTION STATUS:**

- A Inspection complied with @ 2804.7 hours; next due @ 3004.7 hours
- B Inspection complied with @ 2804.7 hours; next due @ 3204.7 hours
- C Inspection complied with @ 2497.4 hours; next due @ 3697.4 hours
- D Inspection due @ 5000 hours
- LH Engine HSI complied with @ 1151.8 engine hours; next due
  @ 2951.8 engine hours In process May 2020
- RH Engine HSI complied with @ 1852.6 engine hours; next due
  @ 3652.6 engine hours
- LH & RH Engine OVH due @ 3600 engine hours

#### **MAINTENANCE PROGRAMS:**

• TRAXXALL Maintenance Tracking Program

#### **INTERIOR:**

New Interior in 2010 by Elliott Aviation. Standard center club eight (8) place seating with seven chairs and canted-aisle facing lav seat covered in Tan Leather. Rice Ultraleather headliner. Tan Leather sidewalls with Chocolate Truffle accent panel. Pebble Taupe carpet. Forward left-side galley and drinkrails covered in rich, Quarter Wenge Mahogany with Black Pearl Satin plating throughout.

#### **EXTERIOR:**

New Exterior in 2010 by Elliott Aviation. Overall Matterhorn White with Silver Platinum Metallic and Phantom Gray Metallic Accent Stripes.

S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



S/N RK-339 N404LR



## MEET THE MANAGEMENT TEAM



































#### **About Holstein Aviation**

- Over \$10 Billion Dollars In Sales
- ▶ Ranked Top 10 Brokerage Firms Worldwide For Transaction Volume
- ▶ 300 Years Of Domestic And International Experience
- ▶ 4,700 Transactions Completed



Proven Professionals. Trusted Partners.









Holstein Aviation, Inc. 4000 West 106th Street, Suite 160 Carmel, IN 46032 USA

+1 (317) 815-9403 1 (877) 530-JETS (5387) US toll free www.holsteinaviation.com