2004 Beechcraft Premier I, S/N RB-93













S/N RB-93 N322BJ

AIRCRAFT LISTING DETAILS:

Total Hours: 2,118.1

Total Landings: 1,580

Engines: Williams FJ44-2A

#1

#2

Total Hours: 2,118.1 2,118.1

Engine Cycles: 1,580 1,580

Serial Numbers: 105095 105094

AIRCRAFT HIGHLIGHTS:

- One U.S. Owner Since New
- Low Time
- Engines on TAP Blue-Deferred \$164.51 per Hour per Engine
- Collins ADS-B Out
- DBU 5000 Data Loader
- LoPresti Taxi / Landing Lights
- No Known Damage History

AVIONICS:

- Collins Pro Line 21
- Integrated Avionics Processor System (IAPS)
- Collins Integrated AFD-3010 Electronic Flight Instrumentation System (IFIS)
- Engine Indication System (EIS)
- Collins FGC-3000 Automatic Flight Guidance System
- Dual Collins ADC-3000 Air Data Computers
- Dual Collins AHC-3000 Attitude Heading Reference System (AHRS)
- Single Collins FMS-3000 Flight Management System with Database
- Dual Collins VIR-432 Navigation Receivers
- Single Collins ADF-462 Automatic Direction Finder (ADF)
 Receiver
- Single Collins DME-442 Distance Measuring Equipment (DME)
- Single Collins ALT-4000 Radio Altimeter
- Single Collins GPS 4000S Global Positioning System (GPS)
- Dual Collins TDR-94 Diversity Transponders
- Collins WXR-800 Weather Radar
- Dual dB System Model 438 Audio System
- MDC-3000 Maintenance Diagnostic Computer
- Cabin Paging System with Four Speakers
- L3 Communications FA2100 Cockpit Voice Recorder-30 Minute Recording Time

S/N RB-93 N322BJ

FEATURES/OPTIONS:

- Honeywell Enhanced GPWS
- Three Tube EFIS Display
- Collins ADS-B Out
- Collins TCAS 4000 TCAS II (includes Dual Collins TDR-94 Diversity Transponders)
- Dual Collins VHF-422C VHF Communication
- Emergency Locator Transmitter
- LoPresti Taxi / Landing Lights
- 2 110 VAC Personal Computer Power Outlets
- 90 Oz. Carpet with Standard Colors and Weave
- Relief Tube Lavatory
- Aft Baggage Heat
- Two Bose Headsets AHX-32-01
- Leather Table Worksurface
- Enclosed Window Shades
- Remote Low Engine Oil Sensor System
- Right Side Ice Light
- 77 Cu. Ft. Oxygen System
- Remote Control Entry Lighting
- Aft Maintenance Bay Lighting
- Refreshment / Hang Up Baggage Cabinet
- Locking Fuel Caps
- Cockpit Sliding Door
- Custom Color Carpet
- Non-Standard Leather Seats (2 Cabin, 2 Crew)

- Non-Standard Leather Console Cap
- Non-Standard Leather Lower Console
- Interior Metal Plating Smoked Nickel
- Custom Paint Scheme

INSPECTION STATUS:

- A Inspection complied with @ 1797.5 hours; next due @ 2397.5 hours
- B Inspection complied with @ 1197.3 hours; next due @ 2397.3 hours
- MLG Gear/Structure Inspection due @ 5000 cycles
- LH & RH Engine HSI due @ 2500 engine hours
- LH & RH Engine OVH due @ 5000 engine hours

MAINTENANCE PROGRAM:

 Engines Enrolled on TAP Blue-Deferred - \$164.51 per Hour per Engine

S/N RB-93 N322BJ

INTERIOR:

- Headliner: Light Oyster Stretch
- Console Cap: Custom Sienna Leather
- Upper Console: Buff Leather
- Lower Console: Custom Sienna Leather
- Upper Partition Mirror: Bronze Jet Mirror
- Floor Covering: Custom Boardwalk Truffle Carpet
- Table Worksurface: Buff Leather
- Cabin / Cockpit Chairs: Custom Sienna / Buff Leather

- Chairs Seatbelts / Harness: Fawn
- Metal Plating: Smoked Nickel
- Laminate: Cognac Birdseye

EXTERIOR:

Overall Matterhorn White with Custom Burgundy, Light Saddle and Black Metallic Stripes

S/N RB-93 N322BJ



S/N RB-93 N322BJ



S/N RB-93 N322BJ



S/N RB-93 N322BJ



S/N RB-93 N322BJ




S/N RB-93 N322BJ



S/N RB-93 N322BJ



S/N RB-93 N322BJ



S/N RB-93 N322BJ



MEET THE MANAGEMENT TEAM



































About Holstein Aviation

- Over \$10 Billion Dollars In Sales
- ▶ Ranked Top 10 Brokerage Firms Worldwide For Transaction Volume
- ▶ 300 Years Of Domestic And International Experience
- ▶ 4,700 Transactions Completed



Proven Professionals. Trusted Partners.









Holstein Aviation, Inc. 4000 West 106th Street, Suite 160 Carmel, IN 46032 USA

+1 (317) 815-9403 1 (877) 530-JETS (5387) US toll free www.holsteinaviation.com