





2008 Hawker 750 | N770GS

Serial Number HB-3

Airframe Total Time (as of 2/4/2020) 1,172.7 Hours 1,087 Landings



Engine Total Time (as of 2/4/2020)

#1 1,172.7 Hours 1,087 Cycles

#2 1,172.7 Hours 1,087 Cycles

APU Total Time (as of 2/4/2020) 1,437 Hours Engines Honeywell TFE-5BR-1H

Engines on MSP Gold

APU on MSP Gold

Contact Brad Stancil +1 (317) 815-9403 Info@HolsteinAviation.com

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice. Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA



Aircraft Highlights

- One Corporate U.S. Owner / One Crew Since New
- Engines & APU on MSP Gold
- Avionics on CASP
- Collins Modernization Package
- WAAS / LPV / ADS-B Out
- Synthetic Vision
- DBU-5000 Data Loaders
- Dual Collins HF-9000 with SELCAL
- Honeywell Solid State Flight Data Recorder
- Paperless Cockpit / Electronic Charts
- New Carpet & Sidewalls June 2019
- No Known Damage History (Note: Tail cap replaced with new part due to lightning strike; logbook entry available upon request)

Inspection & Maintenance History

400 Hour Walk Around complied with @ 802.9 hours; next due @ 1202.9 hours B1-B10 Inspection complied with @ 802.9 hours; next due @ 1602.9 hours C1-C10 Inspection due @ 1600.0 hours D1-D10 Inspection due @ 3200.0 hours E1-E10 Inspection complied with July 2019; next due June 2020 F1-F10 Inspection complied with June 2018; next due May 2020 G 48 Month Inspection complied with June 2016; next due July 2020 48 Month Structurals complied with June 2016; next due July 2020 96 Month Structurals complied with June 2016; next due May 2024 15/18 Year 216 Month Inspection due May 2023 MLG Gear OVH due at 5000 landings; July 2020 LH & RH Engine MPI due @ 2100 engine hours LH & RH Engine CZI due @ 4200 engine hours

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Avionics

Collins Pro Line 21 Avionics **Dual Collins VHF-4000 Comms** Collins NAV-4000 VOR/LOC/GLS/ADF/Marker Beacon Receiver Collins NAV-4500 VOR/LOC/GLS/Marker Beacon Receiver Collins IFIS with single FSU-5010 File Server Unit Collins GPS-4000A Dual TDR-94D Enhanced Surveillance with Flight ID Diversity Transponders **Dual Collins DME-4000 Dual Collins AHC-3000 AHRS** Dual Collins ADC-3000 Air Data Computers Collins FMS-6000 Flight Management Systems Dual Collins CDU-6200 Control Display Units for FMS and Radio Control Collins MDC-3110 Maintenance Diagnostics Computer Dual Collins FGC-3000 Flight Guidance Computers Universal CVR-120 with 2 hour recording capability Collins TWR-850 Turbulence Weather Radar Collins ALT-4000 Radio Altimeter Collins TCAS-4000 TCAS II Artex C406-N ELT Honeywell Mark V EGPWS

Features and Options

XM Graphic Weather Paperless Cockpit Electronic Charts Dual Collins HF-9000 HF Comm System with SELCAL 2nd Collins FMS-6000 FMS/GPS-4000A 2nd Graphical AFD-3010E Display and Cursor Control Panel CCP Honeywell Solid State FDR (SSFDR) 2nd Collins ADF High Intensity Radiated Field (HIRF) Kit AirCell ST3100 Iridium Phone Cabin Audio/Video Entertainment System Airshow 410 System w/Flight Deck Controller 2nd 15" LCD Monitor Power Outlet Package – 110 Enhanced Refreshment Center Package

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Features and Options - continued

Long Range Oxygen (2 x 750 ltr bottles) Precise Flight Pulselite system with TCAS Interface Cabin/Vestibule Hinged Door Wood Veneer Sideledge in lieu of Leather Additional Stowage Drawers under each Club Seat (4) Drop Down Inboard Armrests (all individual chairs) Belted Lavatory Seat Protection Package – Additional Center Aisle Carpet, Set of Throw Rugs, Center Aisle Maintenance Runner, and Threshold Carpet Galley in accordance with design DWG #HB02-87 Galley mods - replace one Mapco with a hot cup. Remove can and other storage space to the right of the Mapco, this area will be used for storage and will have a shelf. Metalwork will be a "brushed" finish instead of "polished". Two shipsets of five (5) cabin chairs and one (1) divan armrest cover Portable oxygen bottle behind forward right hand bulkhead Carpet edges finished with binding Tie down straps for Medical Med Air kits (kit to be provided by customer). Medical Med Air Kit to be located at the aft side of the forward bulkhead of the aft right hand closet. Forward RH baggage with net/webbing fixed on forward side and curtain fixed on forward side Galley Mod: top Kydex insert adjacent to microwave to divide for coffee stirs and creamer/sugar packets Three (3) extra seat belt extensions Pyramid cabinet with can storage

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Exterior





Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Interior – New carpet and sidewalls - June 2019



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice. Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA



Interior - continued



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.



Cockpit



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

- END-