2004 Beechcraft Premier I, S/N RB-92











S/N RB-92 N592HC

AIRCRAFT LISTING DETAILS:

Total Hours: 2,160.5 (as of 6/6/2022)

Total Landings: 1,838

Engines: Williams FJ44-2A

5,000 Hour TBO #1 #2

Total Hours: 2,160.5 2,160.5

Engine Cycles: 1,838 1,838

Serial Numbers: 105093 105092

AIRCRAFT HIGHLIGHTS:

- Low Time
- Engines on TAP Blue \$176.56 per Hour per Engine
- Avionics on CASP
- Collins DBU 5000 Data Loader
- Collins ADS-B Out
- Two Nat'l Aeronautical Assn Speed Records
- CAMP Maintenance Tracking
- No Known Damage History

AVIONICS:

- Collins Pro Line 21
- Integrated Avionics Processor System (IAPS)
- Collins Integrated AFD-3010 Electronic Flight Instrumentation System (EFIS)
- Engine Indicating System (EIS)
- Collins FGC-3000 Automatic Flight Guidance System
- Dual Collins ADC-3000 Air Data Computers
- Dual Collins AHC-3000 Attitude Heading Reference System (AHRS)
- Single Collins FMS-3000 Flight Management System with Database
- Dual Collins VIR-432 Navigation Receivers
- Single Collins ADF-462
- Dual Collins TDR-94 Mode S Transponders
- Single Collins DME-442
- Single Collins ALT-4000 Radio Altimeter
- Single GPS 4000S
- Dual dB Systems Model 438 Audio Systems
- MDC-3000 Maintenance Diagnostic Computer
- L3 Communications FA2100 Cockpit Voice Recorder with 30 Minute Recording Time

S/N RB-92 N592HC

FEATURES/OPTIONS:

- Three Tube EFIS Display
- Collins TCAS 4000 II
- Dual Collins VHF-422C VHF Communication
- Collins TWR-850 Weather Radar
- Honeywell Enhanced GPWS
- Emergency Locator Transmitter
- Collins ADS-B Out
- Collins DBU 5000 Data Loader
- 2 110 VAC Personal Computer Power Outlets
- 90 Oz. Carpet with Standard Colors and Weave
- Aft Baggage Heat
- Two Bose Headsets AHX-02
- Leather Table Worksurface
- Enclosed Window Shades
- Remote Low Engine Oil Sensor System
- Right Side Ice Light
- 77 Cu. Ft. Oxygen System
- Remote Control Entry Lighting
- Aft Maintenance Bay Lighting
- Interior Metal Plating Smoked Nickel
- Relief Tube Cockpit and Aft Lavatory
- Two Stripes ChromaAir Paint
- CAMP Maintenance Tracking

INSPECTION STATUS:

- A Inspection complied with @ 1807.6 hours; next due @ 2407.6 hours
- B Inspection complied with @ 1195.1 hours; next due @ 2395.1 hours
- MLG Gear/Structure Inspection due @ 5000 cycles
- LH & RH Engine HSI due @ 2500 engine hours
- LH & RH Engine OVH due @ 5000 engine hours

MAINTENANCE PROGRAMS:

- Engines Enrolled on TAP Blue \$175.56 per Hour per Engine
- Avionics Enrolled on CASP
- CAMP Maintenance Tracking

S/N RB-92 N592HC

INTERIOR:

- Headliner: Parchment Stretch Crepe
- Console Cap: Shale leather
- Upper Console: Finial Urn fabric
- Lower Sidewall: Platinum leather
- Curtain: Finial Urn fabric
- Upper Partition Mirror: Bronze Jet Mirror
- Floor Covering: Pebble Frieze carpet
- Table Work Surface: Platinum leather
- Cabin/Cockpit Charis: Platinum leather
- Chairs seatbelts/harness: Platinum leather
- Metal Plating: Smoked Nickel
- Laminate: Natural Birdseye Gloss

EXTERIOR:

Overall Matterhorn White with Custom Dark Acanthus and Custom Light Desert Sky Accent Stripe

S/N RB-92 N592HC



S/N RB-92 N592HC



S/N RB-92 N592HC



S/N RB-92 N592HC



S/N RB-92 N592HC



S/N RB-92 N592HC



S/N RB-92 N592HC



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

S/N RB-92 N592HC



MEET THE MANAGEMENT TEAM































About Holstein Aviation

- ▶ Over \$10 Billion Dollars In Sales
- ▶ Ranked Top 10 Brokerage Firms Worldwide For Transaction Volume
- ▶ 300 Years Of Domestic And International Experience
- ▶ 4,700 Transactions Completed



Proven Professionals. Trusted Partners.









Holstein Aviation, Inc. 4000 West 106th Street, Suite 160 Carmel, IN 46032 USA

+1 (317) 815-9403 1 (877) 530-JETS (5387) US toll free www.holsteinaviation.com