



## 1985 Falcon 20-F5 | N404HR

Serial Number 455



### Airframe Total Time (as of 10/10/18)

12,791.8 Hours  
10,295 Landings

### Engine Total Time (as of 10/10/18)

#1 10,707.2 Hours  
8,670 Cycles  
3,136.9 Hours since OVH  
1,347.1 Hours since HSI

### Engines

Honeywell TFE731-5BR



#2 10,552.3 Hours  
8,408 Cycles  
156.7 Hours since OVH  
156.7 Hours since HSI

### APU Total Time (as of 10/10/18)

5,291 Hours

### APU

Garrett GTCP 36-150

**Contact Michael Gauvreau**  
**+1 (317) 815-9403**  
**Info@HolsteinAviation.com**

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

## Aircraft Highlights

- Gear Overhaul - July 2016
- C Check - October 2014
- Thrust Reversers
- Honeywell Mark VII EGPWS with Windshear
- Dual Aircell ST-3100 SATCOMs
- CAMP Maintenance Tracking
- No Known Damage History

## Inspection & Maintenance History

A Inspection complied with Nov 2017 @ 12732.8 hours; next due @ 13032.8 hours / April 2018

2A Inspection complied with Nov 2017 @ 12732.8 hours; next due @ 13332.8 hours / Oct 2018

2A+ Inspection complied with November 2017; next due October 2018

Z Inspection complied with @ 12722.7 hours; next due @ 15122.7 hours

B Inspection complied with @ 12635.1 hours; next due @ 13835.1 hours

2B Inspection complied with @ 11351.8 hours; next due @ 13751.8 hours

3B Inspection complied with @ 9917.5 hours; next due @ 13517.5 hours

4B Inspection complied with @ 8901.2 hours; next due @ 13701.2 hours

C Inspection complied with October 2014; next due October 2020

2C Inspection complied with September 2008; next due December 2020

MLG Detailed Inspection complied with July 2016 @ 10234 landings; next due @ 20234 landings / Nov 2030

LH Engine MPI/HOT complied with @ 9360.1 engine hours; next due @ 11860.1 engine hours

LH Engine CZI/OVH complied with @ 7570.3 engine hours; next due @ 12570.3 engine hours

RH Engine MPI/HOT complied with @ 10395.6 engine hours; next due @ 12895.6 engine hours

RH Engine CZI/OVH complied with @ 10395.6 engine hours; next due @ 15395.6 engine hours

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

**Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA**

---

**+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • [www.holsteinaviation.com](http://www.holsteinaviation.com)**

## Avionics

Dual Collins FD-109 IFCS / Pro Line II  
Dual Collins ADF-60  
Collins AP-105 IFCS Autopilot  
Dual Collins VHF-22 w/8.33 MHz spacing  
Fairchild GA100 Cockpit Voice Recorder  
Dual Collins DME-40 DMEs  
Dual Collins FD-109 IFCS Flight Director  
Dual Honeywell GNS-XLS w/GPS & P-RNAV capability  
Dual Collins VIR-32 w/FM Immunity  
Collins ALT-55 Radar Altimeter  
Dual Aircell ST-3100 SATCOMs  
Honeywell Mark VII EGPWS w/windshear  
Collins TCAS-II w/Change 7  
Dual Collins TDR-94D Transponders  
Honeywell Primus 400 Weather Radar

## Features and Options

Kollsman Digital Pressurization Controller  
Artex 406 ELT  
IS&S Air Data & Altimeters  
BF Goodrich GH-3000 Standby Instruments (coupled to FMS & VOR/ILS)  
Thrust Reversers  
Windshield Embellisher Mod  
Heavy Landing Gear  
SAFT Batteries  
Large Aft Baggage w/PATS APU Installation  
Tel-Tail Lights  
CAMP Maintenance Tracking  
RVSM  
RNP-10

Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

**Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA**

**Exterior** – New Paint in 2008 at West Star Aviation, East Alton, Illinois



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

**Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA**

**+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • [www.holsteinaviation.com](http://www.holsteinaviation.com)**



**Interior** – Interior refurbished in 2008 at West Star Aviation, East Alton, Illinois

Fireblocked tan leather executive ergonomic articulating seats. Matching carpeting. Figured high-gloss veneer cabinetry. Entertainment system with Airshow 400, DVD player with dual screens and 6-disc CD player. 110 outlets in the cabin. Externally-serviceable lavatory.



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • [www.holsteinaviation.com](http://www.holsteinaviation.com)

**Interior – continued**



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

**Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA**

**Interior – continued**



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

**Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA**

**+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • [www.holsteinaviation.com](http://www.holsteinaviation.com)**



**Interior – continued**



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

**Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA**

**+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • [www.holsteinaviation.com](http://www.holsteinaviation.com)**



## Cockpit



Specifications subject to verification upon inspection. Aircraft subject to prior sale without notice.

- END -

Holstein Aviation, Inc. • 4000 West 106th Street, Suite 160 • Carmel, IN 46032 USA

+1 (877) 530-JETS toll free • +1 (317) 815-9403 telephone • +1 (317) 663-0705 facsimile • [www.holsteinaaviation.com](http://www.holsteinaaviation.com)