


Photo of scanning results:



Legend

rebar

Notes

NOT TO SCALE
Wall thickness approx. 8"

Single layer reinforcing.

Recommendation: do not cut any targets. Keep 1" distance between edge of hole and markings.

The results are interpretative in nature and are considered to be a reasonable accurate presentation of existing conditions within the limitations of the radar profiling method. The total aggregate liability of Terraprobe arising from professional acts, errors or omissions shall not exceed the total fees for the services rendered and Terraprobe shall have no other liability, obligation, or responsibility of any kind for losses, costs, expenses, or other damages (including without limitation special, indirect, incidental, or consequential damages) relating to services or results provided by Terraprobe. All results provided by Terraprobe are strictly for the use of the Client, and Terraprobe shall not be responsible for any reliance on or any use or interpretation of such results by third parties. Terraprobe shall not be responsible for any loss, damage, or liability arising from any acts by the Client, its agents or staff or other consultants employed by the Client.



#112 - 17 Fawcett Road Coquitlam, BC V3K 6V2
T: 604 553 4778 - F: 604 243 6993 - E: gpr@terraprobe.com

**XX Cutting & Coring
Page 1 of 1 - Overview**

**Ground Penetrating Radar Survey
Level 1 - Elevator Machine Room**

Terraprobe Geoscience Corp.