

STATE OF TEXAS WELL REPORT for Tracking #391151

Owner: Dan Mullins	Owner Well #: No Data #4
Address: 110 River Crossing Blvd. Spring Branch , TX 78070	Grid #: 68-03-3
Well Location: 1900 FM 473 Kendalia , TX 78027	Latitude: 29° 59' 44" N
Well County: Kendall	Longitude: 098° 37' 50" W
Elevation: No Data	GPS Brand Used: No Data
Type of Work: New Well	Proposed Use: Domestic

Drilling Started: **2/18/2015**
Date: Completed: **2/23/2015**

Diameter of Hole: Diameter: **8.5 in From Surface To 520 ft**

Drilling Method: **Air Rotary**

Borehole Completion: Other: **Cased top to bottom**

Annular Seal Data: 1st Interval: **From 0 ft to 240 ft with 48 sk cem./gel (#sacks and material)**
2nd Interval: **No Data**
3rd Interval: **No Data**
Method Used: **Tremie**
Cemented By: **Davenport Drilling**
Distance to Septic Field or other Concentrated Contamination: **No Data**
Distance to Property Line: **No Data**
Method of Verification: **No Data**
Approved by Variance: **No Data**

Surface Completion: **Surface Slab Installed**

Water Level: Static level: **245 ft. below land surface on 2/18/2015**
Artesian flow: **No Data**

Packers: **Rubber 2 at 240'**

Plugging Info: Casing left in well: Cement/Bentonite left in well:
From (ft) To (ft) From (ft) To (ft) Cem/Bent Sacks Used
N/A

Type Of Pump: **Other: Not installed**
Depth to pump bowl: **(No Data) ft**

Well Tests: **Pump**
Yield: **16 GPM with 61.5 ft drawdown after 21 hours**

Water Quality: Type of Water: **good**
Depth of Strata: **120 ft.**
Chemical Analysis Made: **No**
Did the driller knowingly penetrate any strata which contained undesirable constituents: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the log(s) being returned for completion and resubmittal.

Company Information: **Davenport Drilling & Pump Service**
11844 Bandera Rd #711
Helotes , TX 78023

Driller License Number: **2669**

Licensed Well Driller Signature: **Dean Davenport**

Registered Driller Apprentice Signature: **No Data**

Apprentice Registration Number: **No Data**

Comments: **No Data**

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking number (Tracking #391151) on your written request.

Texas Department of Licensing & Regulation
P.O. Box 12157
Austin, TX 78711
(512) 463-7880

DESC. & COLOR OF FORMATION MATERIAL

From (ft) To (ft) Description
0 to 206' Upper Glenrose
206 to 360' Lower Glenrose
360 to 398' Bexar Shale
398 to 478' Cow Creek
478 to 520' Pine Island Shale

CASING, BLANK PIPE & WELL SCREEN DATA

Dia.	New/Used	Type	Setting From/To
4.5	New	PVC SDR17	0-520'
		Screen	480 to 380 SDR17